TECHNICAL DATA SHEET





SAFETY TECHNICAL SPECIFICATIONS

SAFELY TECHNICAL SPECIFICATIONS			
Description	Measurement Unit	Requirement	Test Result
TOE CAP: Impact resistance	mm	≥ 14	17,5
TOE CAP: Compression resistance	mm	≥ 14	19
ANTI-PUNCTURE PLATE: Penetration resistance	Ν	≥ 1.100	1363
FOOTWEAR: Antistatic properties (in wet condition)	MΩ	≥ 0,1	34,4
FOOTWEAR: Antistatic properties (in dry condition)	MΩ	≤ 1.000	351
UPPER: Water vapour permeability	mg/cm2*h	≥ 0,8	9,7
UPPER: Water vapour coefficient	mg/cm2	≥ 15	82,9
UPPER: Water penetration after 60 min	g	≤ 0,2	-
UPPER: Water absorption after 60 min	%	≤ 30	-
INTERNAL LINING: Water vapour permeability	mg/(cm2*h)	≥ 2,0	85,5
INTERNAL LINING: Water vapour coefficient	mg/cm2	≥ 20	725,9
OUTSOLE: Abrasion resistance	mm3	≤ 150	80
OUTSOLE: Energy absorption of seat region (E)	J	≥ 20	34
OUTSOLE: Flexural resistance	mm	≤ 4	0
OUTSOLE: Interlayer bond strength	N/mm	≥ 4	6,3
OUTSOLE: Resistance to fuel oil (FO)	%	≤ 12	3,9



TRACTION STABILITY GRIP BRAKING SELF-CLEANING LADDER GRIP

ADDITIONAL FEATURES

Test	Measurement Unit	Requirement	Results
Electrical resistance for ESD footwear	MΩ	≤ 1,00	-
Resistance to hot contact (HRO)	-	autsoles shall not melt and develop any cracks when bent	-
Cold insulation of outsole complex (CI) 30min/-17°C (temperature decrease on the upper surface of the insock)	°C	≤ 10	-
Heat insulation of outsole complex (HI) 30min/150°C	°C	≤ 22	-
Water resistance (WR)	cm2	after 80 min.	-
Electric hazard resistance (EH) 18kV / 60 Hz	MΩ	≤ 100	-



	0	MINIMUM VALUE REQUIRED	20	TEST RESULT 35	+	75%
--	---	---------------------------	----	----------------	---	-----

INDUSTRIES

*	×	©	Ż	0		
			 Ö.o		Ĺ	1

STORAGE, CARE AND MAINTENANCE

• PANDA SAFETY footwear should be stored in original packaging, storage temperature should not exceed 35°C, humidity should be less than 80% and without the influence of direct sunlight.

• Sandals, shoes and boots should be cleaned after each use; dry off the shoes, not in proximity to or in direct contact with stoves or other sources of heat.

• Carry out the periodic treatment of the uppers with suitable products containing wax, grease, silicone, etc.

• Avoid contact with aggressive chemicals and extreme temperatures.

• Verify the good state before each use.

All data provided in this technical data sheet are subject to modification without notice in the event of evolution in materials and/or components. All rights reserved. No part of this technical sheet can be reproduced in any form without the written consent of PANDA SAFETY

())*(*